

**CASE STUDY** 

# **Offshore Rope Access and Rigging Services**

### Challenge

Cost effective installation of lateral tension rings on the conductor at the spider deck level of platform.

## **Solution**

- Remove the tension ring
- Provide expert rope access riggers to "cross Haul" the 1.5 ton tension ring system
- Remove four hydraulic cylinders
- remove four 30ton sling sets from around main structure
- Project management, planning and execution
- Maintaining safe methods of work
- Provide full equipment certification, management and tracking system





#### Result

- Tension ring system removed
- Maintaining safe systems of work during rope access operations
- No reportable lost-time incidents

## **Maximising our value**

- Maintaining client's safety culture
- Reduction in offshore remedial works due to closing-out all defects whilst on-site
- Provide technical advice and assistance
- Completing work scopes within designated timescales thus reducing costs of return visits

#### www.3sungroup.com

#### enquiries@3sungroup.com

#### +44 (0)1493 666266

The Expertise Behind Servicing the World's Energy Industry